Page 3

Application/Control Number: 10/670,967

Art Unit: 3635

In claim 2, line 3, "the upper" has been replaced with - - said first outer - -.

In claim 2, line 5, "the lower" has been replaced with - -said second outer - -.

In claim 2, lines 34, "the lower" has been replaced with - -said second outer - -.

In claim 2, line 6, "the lower" has been replaced with - -said second outer - -.

In claim 2, line 8, "section" has been replaced with - - sections - -.

In claim 2, line 8, "the upper" has been replaced with - - said first outer - -.

## Claim 12:

In claim 12, line 5, "section" has been replaced with - -sections - -.

In claim 12, line 6, "post" has been replaced with - - posts - -.

In claim 12, line 11, "a lower" has been replaced with - - a first outer - -.

In claim 12, lines 11-12, "the lower" has been replaced with - -said first outer - -.

In claim 12, line 14, "a upper" has been replaced with - -a second outer - -.

In claim 12, line 14, "the high" has been replaced with - -said second outer - -.

In claim 12, line 16, "the lower" has been replaced with - -said first outer - -.

In claim 12, line X, "the upper" has been replaced with - - said second outer - -.

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Yvonne M. Horton whose telephone number is (571) 272-6845. The examiner can normally be reached on 6:30 am - 3:00 pm.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Naoko Slack can be reached on (571) 272-6848. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

98

JB1129106

991129106